

A FUNNY THING HAPPENED ON THE WAY TO THE FORUM

Lightbridge (US+DS)

Notes

- Hang MAC301 with inputs/outputs facing upstage.
- Please orient PAR64 bottles going SR-SL
- DMX and 208v will be dropped from SL Gallery.
- Please chain DMX for MAC301 from SL to SR
- 208v Line 1 and 2 will be dropped. Please three-fer MAC301 Unit 6, 11, and 16 on Line 1. Please two-fer MAC 301 unit 21 and 26 on Line 2.
- Note 750W on 36degree and 50degree. See ME for lamps.
- Please remember to pull all shutters.
- See ME with any questions.

INSTRUMENT COUNT

20 x PAR64

12 x Source 4 26degree

1 x Source 4 36degree (750W)

1 x Source 4 50degrees (750W)

5 x MAC301

A FUNNY THING HAPPENED ON THE WAY TO THE FORUM

Electric 1

Notes

- Please pay attention to two-fers. They are highlighted on paperwork and plotstrip.
- 4-Pin will be dropped from SL Gallery.
- Please chain Colorscrollers from SL to SR. Addresses are on LW paperwork.
- Please remember to pull all shutters.
- See ME with any questions.

INSTRUMENT COUNT

29 x Source4 36degree
6 x Colorscrollers

DROPBOXES

SL: L1/8 (circuits
L2/6 (circuits
SR: R1/8 (circuits

A FUNNY THING HAPPENED ON THE WAY TO THE FORUM

Electric 2

Notes

- Please Hang MAC301's with inputs/outputs facing upstage
- Please pay attention to two-fers. They are highlighted on paperwork and plotstrip.
- Please orient PAR64 bottles SL to SR.
- DMX and 208v will be dropped from SL Gallery.
- Please chain DMX for Martin Strobe and MAC301's from SL to SR (one chain)
- 208v line 3, 4, and 5 will be dropped from SL Gallery. Please three-fer MAC301 units 4, 9, and 14 on Line 3. Please twofer MAC301 units 19 and 24 on Line 4. Please plug Strobe into Line 5.
- See ME with any questions.

INSTRUMENT COUNT

20 x PAR64

5 x MAC301

1 x Martin Strobe

DROPBOXES

SL: L4/4 (circuits

SR: R2/8 (circuits